

PS II Redundant PSU Installation Guide



ATC MB Tray Installation Guide







■ When you use ATX PSU , Please use four #6-32 screws to fasten the ATX adaptor plate to the








3 Please install the above assembly unit into the




frame and fasten it by four #6-32 screws (As (1) left photo 3.4.)



When you use redundant PSU, Please take out the redundant adaptor plate from the accessories pack. (1).





the frame and fasten it by four #6-32 Screws (As left photo 2.3.)




2 Please install the above assembly unit into

(P/W 3*6 Screws), (Hexagon Screws) Left photo is MB tray, which has been fixed twenty four stand-off.







2 As Left photo shown, There are eight holes need to be fasten to the MB tray. (It's possible that the MB tray will be able to fit on P4 423).



B Please select the opposite hole location from MB and fasten eight hexagon screws on the MB tray (As left photo shown).



4 Please use eight P/W 3*6 screws to fasten motherboard on the MB tray. (As left photo shown)






6 Assembly has been finished as left photo.


How To Assemble The Top Fan




Remove screws from the usb module.



2 Please put the fan(option) into the fan holder then attach the fan guard(option) with screws.




3 Please fix the fan holder with chassis.



4 Finished.







WAVE MASTER

USER MANUAL

INDEX

ATX PSU Installation Guide 1
PS II Redundant PSU Installation Guide2
ATC MB Tray Installation Guide3
How To Assemble The Top Fan4
Others5

